



STATE OF WASHINGTON
WASHINGTON STATE PATROL
FORENSIC LABORATORY SERVICES BUREAU

2203 Airport Way South, Suite 360 • Seattle, Washington 98134-2027 • (206) 262-6000 • FAX (206) 262-6018

March 31, 2006

DataMaster #949273

On March 21, 2006 it was discovered that DataMaster serial number 949273 located in the Chelan County Jail had not been inspected according to the required WSP Breath Test Section protocol for annual quality assurance inspections.

The instrument was out of compliance between January 1, 2005 and March 21, 2006. There were 371 tests, including 54 refusals, conducted on this instrument during that period.

All law enforcement agencies who conducted those tests were notified of this situation in the days following its discovery. The Washington State Patrol (WSP) has also contacted city and county prosecutors in those jurisdictions and notified them of this oversight. The Department of Licensing (DOL) hearings examiners have also been notified.

If you are an attorney with a client who was tested on this instrument during this period, please contact the appropriate prosecutor's office.

This notice is also being posted on the WSP WebDMS web site.

Barry K. Logan, Ph.D., DABFT
Washington State Toxicologist

